

URGENT SAFETY RECALL AND PRODUCT QUARANTINE
Skyblazer II Red XLT Aerial Signals
November 24, 2025

- A. **Incidence Report.** Orion Safety Products, the manufacturer of the hand-launched **Skyblazer II Red XLT Aerial Signals (“XLTs”)** received a report indicating that an XLT ignited without the safety cap being removed or the ignition cord being pulled. The report and photographs indicate that the flare did not launch but burned in place. There were no reported injuries.
- B. **Impacted XLTs.** As Orion continues to investigate, this recall and product quarantine encompasses all XLT products that were manufactured after February 2025. Below are the impacted Orion product numbers, with the relevant lot numbers and expiration dates:

Product Numbers: 752; 758; 769; 855; 855A and 859

<u>Lot No.:</u>	<u>Expiration Dates:</u>
143	June 2028-Aug 2029
145	Sept. 2028-Nov 2028
147	Dec. 2028-Feb 2029
149	Mar 2029 -Apr 2029

- C. **Quarantine.** As the investigation continues, Orion is directing all customers, distributors, dealers and consumers to:
- Immediately stop using any XLTs with the Lot No. and/or Expiration Dates noted in Section B above.
 - Quarantine all impacted XLTs and store the product in a safe and secure location away from combustible products until further notice.
- D. **Next Steps.** Orion is currently conducting an exhaustive investigation as to the cause of the reported incident. Once more information is known, Orion will contact you to provide more information, including:
- How Orion will arrange for collection/destruction of quarantined product
 - How and when replacement product will be provided

As more information becomes available Orion will post updates on its website at <https://www.orionsignals.com/project/recall-notices/>

Orion is critically concerned about the safety of our customers. We are notifying the U.S. Coast Guard and the Consumer Product Safety Commission of this occurrence. It is imperative you segregate and secure any XLTs that are identified in Section B above as soon as possible. We understand that this is a complex issue and we thank you in advance for your patience and understanding while we continue to investigate this matter and the logistics for moving forward.

PHOTOGRAPHS OF IMPACTED PRODUCTS:



Item No. 752



Item No. 758



Item No. 769



Item No. 855/855A (sold individually)



Item No. 859