

URGENT CIL/ORION SKYBLAZER SAFETY RECALL AND PRODUCT QUARANTINE FOR CANADIAN MARKET

UPDATED JANUARY 14, 2026

A. Incidence Report. Orion Safety Products, the manufacturer of the hand-launched CIL/Orion Skyblazer Twin Red Aerial Flares and Orion Search and Rescue Self-Contained Aerial Flares (“Skyblazers”) received a report indicating that a Skyblazer-type product manufactured for the U.S. market ignited without the safety cap being removed or the ignition cord being pulled. The report and photographs indicate that the flare did not launch but burned in place. There were no reported injuries.

B. Impacted Skyblazers. As Orion continues to investigate, this recall and product quarantine encompasses all Skyblazer products that were manufactured after February 2025. Below are the impacted Orion product numbers, with the relevant lot numbers and expiration dates:

Orion Product Numbers: 699; 946; 752 and 758

Lot No. 13; Manufacture Dates: Mar 2025 – July 2025

C. Quarantine. As the investigation continues, Orion is directing all customers, distributors, dealers and consumers to:

- Immediately stop using any Skyblazers with the Product Number, Lot No. and/or Expiration Dates noted in Section B above.
- Quarantine all impacted Skyblazers and store the product in a safe and secure location away from combustible products until further notice.

D. Next Steps. Orion is currently conducting an exhaustive investigation as to the cause of the reported incident. Once more information is known, Orion will contact you to provide more information, including:

- How Orion will arrange for collection/destruction of quarantined product
- How and when replacement product will be provided

As more information becomes available Orion will post updates on its website at

<https://www.orionsignals.com/project/recall-notice/>

Orion is critically concerned about the safety of our customers. We are notifying the U.S. Coast Guard and the U.S. Consumer Product Safety Commission of this occurrence. It is imperative you segregate and secure any Skyblazers that are identified in Section B above as soon as possible. We understand that this is a complex issue and we thank you in advance for your patience and understanding while we continue to investigate this matter and the logistics for moving forward.